




1/10




2/10







٦.










Page 27 of 32



F1G. 6







·. .

726 UT of Creviced or Tee-Box to Pipe Weld with No Indications (BWRVIP-i8)		
Petails Details Details Details	Deals	Petalis
72.2 Next Required Exam MAR-2002 MAR-2006 MAR-2006 MAR-2006 MAR-2000 MAR-2	MAR-2002 MAR-2002	OCT-2001
	z z	Z
F1G, 10, 10, 10, 10, 10, 10, 10, 10, 10, 10	- >	>
716 Last Inspectio MAR-1998 MAR-1998 MAR-1998 MAR-1998	MAR-1996	OCT-1999
712 714 UT UT UT EVT-1	5	FX:
630 702. Junition Box Loop A@ Syring Horizontal Pipe To Junction Box Loop A@ Sy Azimuth Horizontal Pipe To Elbow Loop A@ S. Azimuth Elbow To Pipe Downcomer Loop A@ 80' Downcomer To Elbow Weld Loop A@ 80' Azimuth Lower Elbow To Shroud Pipe Weld Loop A@ 80' Azimuth Siiding Sleeve To Upper Downcomer Loop A@ 80' Downcomer Siiding Sleeve Weld To Outrer Sleeve Weld To	80° Downcomer Outer Sleeve To Lower Downcomer Weld Loop A	Collar Weld To Shroud Pipe Loop A @ ED* Downcomer
770 Veld 193 1948 1940 195 195 196	Ľ.	1P8A